

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| F. E. | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| | |
|--------------------------------|---|
| 5a. Indicate Type of Lease | |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|--|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- D & A | | 7. Unit Agreement Name |
| 2. Name of Operator Brooks Exploration Incorporated - Robert Mead | | 8. Farm or Lease Name McAuliffe Ranch |
| 3. Address of Operator 2110 Western Federal Savings Bldg., Denver, Colorado 80202 | | 9. Well No. 2 |
| 4. Location of Well UNIT LETTER 0, 660 FEET FROM THE South LINE AND 3300 FEET FROM THE West LINE, SECTION 21 TOWNSHIP 30 North RANGE 24 East NMPM. | | 10. Field and Pool, or Wildcat Wildcat |
| 15. Elevation (Show whether DF, RT, GR, etc.) 6308' Ground | | 12. County Colfax |

| | | | |
|--|---|--|--|
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data | | | |
| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 950'. Niobrara 518 (+5790), McAuliffe Sands 606(+5702)
Sill #1 698(+5610) - 55' thick, Sill #2 945(+5363)
Slight show of water at 400' and in Sill #1. Sill # 2
had water flow estimated at 30 gal/minute. Had hole full
of water overnight.

Plugged with 25 sxs. on bottom, 25 sxs. across 7" casing,
10 sxs. on top. Heavy mud between plugs.

Casing in hole - 10-3/4" at 56', 7" at 593', cemented to surface.
Plugged and abandoned 6-15-78.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED William R. Clark TITLE Geologist DATE 6-16-78
APPROVED BY Carl Ulvog TITLE SENIOR PETROLOGICAL ENGINEER DATE 5/1/83
CONDITIONS OF APPROVAL, IF ANY: