



Attachment's H and I are water analysis for the Vermejo Ranch 3-1 and Leandro Creek No. 1. Attachment J is test information on the Vermejo Ranch 3-1 is also enclosed. We have been unable to get a sustained test on the Leandro Creek No. 1 at this date; however, when we do, I will forward it to you.

Attachment K is gas analysis reports for the Van Bremmer 30-33, Vermejo 2-1 and the Vermejo 3-1.

Pennzoil is currently in the process of making application for non-standard locations for the Vermejo Ranch 3-1 and Leandro Creek No. 1. This was an oversight on Pennzoil's part. All adjacent lands and the minerals in this area are owned by Pennzoil Company.

Sincerely,

PENNZOIL COMPANY

A handwritten signature in dark ink, appearing to read "D. R. Hardy", written over the printed name and title.

David R. Hardy  
District Engineer

053DRH  
DRH/cmf