Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Revised March 25, 1999 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-007-20120 District II OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III STATE FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A VPR 'A' DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Coalbed Methane 2. Name of Operator 8. Well No. - 21 SONAT RATON, L.L.C. 9. Pool name or Wildcat Address of Operator P.O. Box 190; Raton, NM 87740 4. Well Location feet from the South line and 1887.45 feet from the Unit Letter O: 1195.39 line East 31 Township 32 N Range 20 E NMPM Colfax Section County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 8058'(GR) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND TEMPORARILY ABANDON CHANGE PLANS **ABANDONMENT** CASING TEST AND PULL OR ALTER CASING MULTIPLE **CEMENT JOB** COMPLETION OTHER: COMPLETION OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Perforate casing 2212 - 2216 W/4 SPF. Frac 2212 - 2216 W/50,000 lbs. of sand. Set RBF @ 2200'. Perforate casing 2178 – 2182 W/4 SPF. Well went on vacuum. Set RBP @ 2160. Perforate casing 2142 - 2146 W/4 SPF. Frac 2142 - 2146 W/50,000 lbs. Set RBP @ 2080. Perforate casing 2003 - 2007, 1996 - 2000, 1987 - 1991 W/4 SPF. Frac 1987 - 2007 W/186, 544 lbs of sand. Clean out casing to 2382. Run production equipment (PC Pump). BJ Services mixed & pumped 100 sks PLHS plus additives down the annulus. Pumped @ 85 PSI @ 1/2 BPM. ISIP - 100 PSI. I hereby certify that the information above is true and complete to the best of my knowledge and belief. / TITLE Sr. Petroleum Engineer DATE 09/30/99 Telephone No. (505) 445-4621 Type or print name Donald R. Lankford (This space for State use) TITLEDISTRICT SUPERVISOR APPPROVED BY

Conditions of approval, if an