

Johnson, Roy

From: Johnson, Roy
Sent: Friday, June 21, 2002 1:03 PM
To: 'don.lankford@elpaso.com'
Subject: Well 'E' 34

Don, as you are probably aware the above referenced well failed the mechanical integrity test. No injection will be allowed until this disposal well can pass a MIT test. I also observed a pit on this location and if it remains it will have to be permitted through our environmental group.

Have a nice weekend.
ROY