

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. --
7. Unit Agreement Name --
8. Farm or Lease Name Vaughn State
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Guadalupe

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Wildcat
2. Name of Operator Petroleum Development Corporation
3. Address of Operator 9720-B Candelaria N.E., Albuquerque, N.M. 87112
4. Location of Well UNIT LETTER E, 682 FEET FROM THE West LINE AND 2026 FEET FROM THE North LINE, SECTION 16 TOWNSHIP 6N RANGE 17E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 5744 CL

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned 6/15/74 after receiving verbal approval and instructions from the Commission as follows:

- 20 sx. cement on bottom 503-526'.
- 20 sx. cement across base of 10-3/4" casing, 211-244.
- 5 sx. cement in top of 10-3/4" casing.

Welded a steel plate across top of casing and installed 4" pipe marker with well identification data.

Notification will be made as soon as pits are filled and location restored.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles W. Sanders TITLE Vice President Engineering DATE 6/24/74
Charles W. Sanders
APPROVED BY Carl Ulvog TITLE SENIOR PETROLEUM GEOLOGIST DATE 7/29/76
CONDITIONS OF APPROVAL, IF ANY: