



**Amoco Production Company**

November 6, 1987

File: WF

Re: Multipoint Back Pressure Test  
Bravo Dome Carbon Dioxide Gas Unit  
Well Number 1933-161G \_\_\_\_\_

New Mexico Oil Conservation Division  
P. O. Box 2088  
Santa Fe, NM 87501-2088

Dear Mr. Johnson:

Attached is NMOCD form C-122 for Bravo Dome Carbon Dioxide Gas Unit well number 1933-161G. This well averages approximately 10 MCFD at a flowing tubing pressure of 180 psi. Amoco attempted to perform a 4 point test on this well as required by NMOCD Rule 1122, however the increasing back pressure caused this well to stop flowing. As a result, the test could not be performed.

Consequently, Amoco requests an exception to Rule 1122 for this well. If you have any questions, please let me know.

Thanks,

D J Holcomb

DJH

Attachment