

(One Copy Must Be Filed With Each Completion Report.)

1. FIELD NAME	2. LEASE NAME	Well Number
3. OPERATOR	Bravo Dome Carbon Dioxide Gas Unit	1833-091 G
4. ADDRESS	AMOCO Production Co.	County
5. LOCATION	P.O. Box 606 Clayton, N.M. 88415 T18N R33 E, sec. 9 "G"	

## RECORD OF INCLINATION

[illegible]

If additional space is needed, use the reverse side of this form.

17. Is any information shown on the reverse side of this form? ☐ yes ☒ no
18. Accumulative total displacement of well bore at total depth of 2742 feet = 28.34 feet.
- \*19. Inclination measurements were made in - ☐ Tubing ☐ Casing ☐ Open hole ☒ Drill Pipe
20. Distance from surface location of well to the nearest lease line \_\_\_\_\_ feet.
21. Minimum distance to lease line as prescribed by field rules \_\_\_\_\_ feet.
22. Was the subject well at any time intentionally deviated from the vertical in any manner whatsoever? No
- (If the answer to the above question is "yes", attach written explanation of the circumstances.)

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation tests and obtained the above results.

Drilling Contractor Baker & Taylor Drilling Co.

By David P. Myers

Subscribed and sworn to before me this 5th day of November 1984

Sue Baer  
Notary Public



**SUE BAER**  
Notary Public, State of Texas  
My Commission Expires 6/9/19 88

My Commission Expires:

Potter County, Texas