

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 200-1916 Field: Bravo Dome

Location: 178 Fm x 1400 Fm, T20n, R33E, Sec 14, Unit G

<u>DEPTH</u>	<u>ANGLE INCLINATION DEGREES</u>
500'	$\frac{1}{4}^{\circ}$
750'	$\frac{1}{2}^{\circ}$
1250'	$\frac{3}{4}^{\circ}$
1740'	$\frac{3}{4}^{\circ}$
2240'	$\frac{3}{4}^{\circ}$

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Yang J. Yang (Amico)

_____ (Aztec)
Title: _____