

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2033-201G Field: Bravo Dome

Location: 1980' FNL X 1980' FEL, T20N, R33E, SEC 20, UNIT 6

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>385'</u>	<u>1/4°</u>
<u>706'</u>	<u>3/4°</u>
<u>1191'</u>	<u>3/4°</u>
<u>1685'</u>	<u>1/4°</u>
<u>2154'</u>	<u>1/2°</u>
<u>2460'</u>	<u>3/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Ronnie R. Carr (Amoco)

Buddy Davis
Title: ARTER TOOL PUSHER