

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2033-1716 Field: Bravo Dome

Location: '980' FOL X 1980' FEL T20N, R33E, SEC 17, Unit 7A

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>300'</u>	<u>1/4 °</u>
<u>511'</u>	<u>1/2 °</u>
<u>695'</u>	<u>1 °</u>
<u>1180'</u>	<u>1 1/4 °</u>
<u>1694</u>	<u>1 °</u>
<u>2249</u>	<u>3/4 °</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Larry J. Young (Amoco)

W. H. [Signature]
Title: AMS Toolpusher