

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2033-221X Field: Bravo Dome

Location: 1980 FNL X 1960 FEL T20N, R33E, Sec 22, Unit G

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>233'</u>	<u>1/2°</u>
<u>511'</u>	<u>1/2°</u>
<u>694'</u>	<u>1/2°</u>
<u>1199'</u>	<u>3/4°</u>
<u>1744'</u>	<u>1/2°</u>
<u>2249'</u>	<u>3/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

James L. Long

Kurt J. Long
Title: HWS Toolpusher