

OIL CONSERVATION DIVISION  
RECEIVED

INCLINATION REPORT

'93 JUL 26 AM 10 12

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415


Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-1116 Field: Bravo Dome

Location: 2039' FEL K 2044' FNL T21N, R32E, SEC 11, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>246</u>	<u>1/4</u>
<u>369</u>	<u>1/4</u>
<u>730</u>	<u>1/4</u>
<u>1181</u>	<u>3/4</u>
<u>1654</u>	<u>1°</u>
<u>2128</u>	<u>1°</u>
<u>2430</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.



  
Title: J. R.