

'93 AUG 18 AM 9 08

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-231G Field: Bravo Dome

Location: 1994' FAL X 2071' FNL T21N R32E SEC 23 UNIT 9

| DEPTH       | ANGLE<br>INCLINATION DEGREES |
|-------------|------------------------------|
| <u>58</u>   | <u>1.25</u>                  |
| <u>641</u>  | <u>2.50</u>                  |
| <u>1161</u> | <u>.75</u>                   |
| <u>1620</u> | <u>.75</u>                   |
| <u>2061</u> | <u>1.0</u>                   |
| <u>2409</u> | <u>1.0</u>                   |

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

  
\_\_\_\_\_

  
Title: \_\_\_\_\_