

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415
Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-2619 Field: Bravo Dome
Location: 2001' EEL X 1970' ENL T21N, R32E, SEC 26, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>471'</u>	<u>1/4°</u>
<u>688'</u>	<u>1/2°</u>
<u>1159'</u>	<u>3/4°</u>
<u>1643'</u>	<u>3/4°</u>
<u>2069'</u>	<u>1 1/4°</u>
<u>2430'</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Larry J. Young

Walt Starnes
Title: Bravo Dome Supervisor