

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-362G Field: Bravo Dome

Location: 1965' FEL X 1975' FNL T21N R32E, SEC. 36, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>458</u>	<u>1°</u>
<u>673</u>	<u>2 1/2°</u>
<u>1115</u>	<u>2°</u>
<u>1588</u>	<u>2 3/4°</u>
<u>1682</u>	<u>3 1/4°</u>
<u>1840</u>	<u>2 1/2°</u>
<u>2312</u>	<u>1°</u>
<u>2502</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Robert E. Romo

C. J. Ladson
Title: T.R.