

INCLINATION REPORT

OIL CONSERVATION DIVISION
RECEIVED

'93 JUN 14 AM 9 21

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-021 F Field: Bravo Dome

Location: _____

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>283</u>	<u>1/2</u>
<u>527</u>	<u>3/4</u>
<u>685</u>	<u>1/2</u>
<u>1225</u>	<u>3/4</u>
<u>1632</u>	<u>1 1/4</u>
<u>2043</u>	<u>1 1/4</u>
<u>2190</u>	<u>1 1/4</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Robert E. PerryO. V. Redman
Title: _____