

INCLINATION REPORT

'93 JU 7 AM 8 52

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-0416 Field: Bravo Dome

Location: 1978' FEL X 2021' FNL T21N, R33E, SEC. 04 UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>216'</u>	<u>1/4"</u>
<u>462'</u>	<u>1/4"</u>
<u>681'</u>	<u>1/2"</u>
<u>1160'</u>	<u>1"</u>
<u>1634'</u>	<u>1"</u>
<u>2036'</u>	<u>1"</u>
<u>2568'</u>	<u>1"</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Ronnie R. Cam

Bob D. Dwyer
Title: SITON Tool Pusher