

OIL CONSERVATION DIVISION

RECEIVED

INCLINATION REPORT

'93 JUN 24 AM 8 55

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-051G Field: Bravo Dome

Location: 1793' FEL x 2024' FNL, T21N, R33E, SEC05, UNIT-G

DEPTH	ANGLE INCLINATION DEGREES
<u>437</u>	<u>1/4°</u>
<u>684</u>	<u>3/4°</u>
<u>1148</u>	<u>1°</u>
<u>1619</u>	<u>1°</u>
<u>2568</u>	<u>1°</u>
<u> </u>	<u> </u>
<u> </u>	<u> </u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Monte J. De la

Paul S. Smith
Title: Area Toolpusher