

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-061G Field: Bravo Dome

Location: 2002' FEL x 1996' ENL, TRIN, R33E, SEC 06, UNIT 6

DEPTH	ANGLE INCLINATION DEGREES
<u>425'</u>	<u>1/2°</u>
<u>707'</u>	<u>3/4°</u>
<u>1127'</u>	<u>3/4°</u>
<u>1651'</u>	<u>1°</u>
<u>2143'</u>	<u>1°</u>
<u>2625'</u>	<u>1 3/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Ronnie R. Carman

Ante Tootygher
Title: Ante Tootygher

RECEIVED
JUN 21 1971
CONSERVATION DIVISION