

OIL CONSERVATION DIVISION
REGISTERED

'93 JUN 17 AM 8 56

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-101J Field: Bravo Dome

Location: 1889' FFL x 2007' FSL, T21N, R33E, Sec 10, Unit J.

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>499</u>	<u>1/4</u>
<u>716</u>	<u>1/4</u>
<u>1187</u>	<u>1/4</u>
<u>1605</u>	<u>1/2</u>
<u>2099</u>	<u>1/2</u>
<u>2386</u>	<u>1</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

[Signature]

[Signature]
Title: Antec Toolpusher