

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-1616 Field: Bravo Dome

Location: BRavo DOME HARDING Co. N.M.
1873 FEL X 2154 RAIL, T3N. R33E, SEC 16, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>529</u>	<u>3/4</u>
<u>683</u>	<u>3/4</u>
<u>1155</u>	<u>1/2</u>
<u>1628</u>	<u>3/4</u>
<u>2101</u>	<u>1°</u>
<u>2443</u>	<u>1/2</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

J. P. Smith
AMOCO

C. L. Ladd
Title: T.P.