

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-201G Field: Bravo Dome

Location: 1982' FEL Y 1968' FNL T21N R33E SEC 20 UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>498</u>	<u>2 1/2°</u>
<u>529</u>	<u>2°</u>
<u>694</u>	<u>1 1/4°</u>
<u>1187</u>	<u>1°</u>
<u>1661</u>	<u>1°</u>
<u>2134</u>	<u>1°</u>
<u>2460</u>	<u>3/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Robert E. Bray

C. D. Redman
Title: T.P.