

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2116 Field: Bravo Dome

Location: B D C O G U 2133
2008' FEL X 1986 FNL, T21N, R33E, SEC-24, UNIT G

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>429</u>	<u>1°</u>
<u>644</u>	<u>1°</u>
<u>1115</u>	<u>1°</u>
<u>1588</u>	<u>1°</u>
<u>1936</u>	<u>1 3/4°</u>
<u>2508</u>	<u>1 1/2°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

J. R. Kehler

C. D. Ledgman
Title: T. P.