

'93 JUL 9 AM 8 41

INCLINATION REPORT


Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415


Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-2816 Field: Bravo Dome

Location: 2085' FEL X 2153' FNL T21N R33E SEC 28 UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>459'</u>	<u>1/2°</u>
<u>674'</u>	<u>3/4°</u>
<u>1114'</u>	<u>1 1/4°</u>
<u>1840'</u>	<u>1°</u>
<u>2313'</u>	<u>1°</u>
<u>2598'</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: J. R.