

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-3016 Field: Bravo Dome

Location: 1971 FEL X 2148' FNL, T21N, R33E, SEC 30, UNIT 6

DEPTH	ANGLE INCLINATION DEGREES
<u>459'</u>	<u>3/4°</u>
<u>675'</u>	<u>1°</u>
<u>1143'</u>	<u>1°</u>
<u>1618'</u>	<u>1 1/4°</u>
<u>2091'</u>	<u>1°</u>
<u>2501'</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Ronnie R. Lane

C. J. Ladd
Title: _____