OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

INSPECTION REPORT

ROY E. TIMMONS AND/OR TIMMONS CARNONIC COMPANY

RE: #1 Timmens
SWNE Sec. 33-T21N-R30E
#1 Kerlin
SWNE Sec. 34-T21N-R30E
#1 Tixier
SWNE Sec. 2-T20N-R30E
HARDING COUNTY

On this day I visited the Timmens carbon diexide processing plant and the three above captioned wells at the Bueyeres vicinity of Harding County. I have found the plant completely shut down and not in operation and the living quarters presently unsecupied. Concerning the above wells the #1 Timmens is connected up to the plant with a 4" (apprex.) pipe line laid on the surface of the ground. It has what appears to be a proper well head connection and metering device although the meter shows evidence of not having been in working order for several months time. The master valve at this well is epen and the line to the plant is live with carbon diexide gas. The #1 Kerlin well is likewise capped and connected up to the plant. However the well-head connections are very correded and are leaking gas at the surface. I am not aware of any metering device's being used at this well. The #1 Tixler well is as the writer reported it on February 3, 1954, in effect, apparently plugged and abandened and with a 6" marker pipe in place at the well bere. However, since that report, we have received an account from Mr. Timmens to the fact that this well was drilled to a total depth of 987' and that casing was run and cemented to this depth. Details on the casing or the cement job were not made available. Mr. Timmens however, has expressed a desire to retain this well as it new stands until such time as he is able to either deepen or plug back for carbon discide production.

OIL CONSERVATION COMMISSION

P. O. BOX 271

SANTA FE, NEW HEXICO

The second secon

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

-2-Inspection Report

I talked with Mr. Frank Andreda, the plant foreman, at his home in Mesquere and he revealed the fact that the plant was in operation until October 14, 1954. Mr. Andreda said also that operations were new suspended in anticipation of the installation of a new gas compresser at which time the operator expected to resume plant production again.

EUGENE A. CHAVEZ Oil & Gas Inspector

sk

O'L CONSERVATION COMMISSION P. O. BOX 971

SANTA FEL NEW MEXICO