



Post Office Box 1668 / Albuquerque, New Mexico 87103 / (505) 843-6762



Reference _____

Case 7638

NMOCD
Attn: Roy Johnson
P.O. Box 2088
Santa Fe, New Mexico 87501

Dear Mr. Johnson:

Enclosed please find C105's, C103's and logs on the Clyde Berlier #1 and Clyde Berlier #2. On the Mora Ranch #3 and Mora Ranch #4 I have enclosed some logs. This all the information I could find.

Clyde Berlier #1	P & A
Clyde Berlier #2	P & A
Mora Ranch #3	P & A, but because the rancher ran us off we are now in Federal Court on this matter we could not put a dry hole marker on the locaton.
Mora Ranch #4	P & A, SI, the rancher ran us off after a frac job and we can't re-enter the location until the issue is decided in federal court.
Simms Ranch #1	SI We were not the operator when it was drilled, but later assumed operations.

If there are any questions please give me a call.

Sincerely,

Anita Vigil
Anita Vigil