

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONFIDENTIAL

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Coronado Exploration Corp.		8. Farm or Lease Name Mora Ranch
3. Address of Operator 1007 Marquette N.W. Albuquerque, NM 87102		9. Well No. #4
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>south</u> LINE AND <u>610</u> FEET FROM THE <u>west</u> LINE, SECTION <u>5</u> TOWNSHIP <u>21N</u> RANGE <u>21E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 6520 Gr		12. County Mora

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 597' of 7" casing and cemented with 130 sacks of cement.
Drilled to TD of 801'. Encountered water at 801' (Greenhorn lime). Water rose to 400' from surface.
Set 25' cement plug from 775'-800' to stop water. Shut in well WOC.
Blew hole dry and waited 12 hrs. to check for reentry of water. No water reentered.
Moved rig from location. 1/9/79

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CORONADO EXPLORATION CORP.

SIGNED BY: Kathy Ballard TITLE Production Dept. DATE January 25, 1979

APPROVED BY: Carl Ulvog TITLE SENIOR PETROLEUM GEOLOGIST DATE 1/29/79

CONDITIONS OF APPROVAL, IF ANY: