STATE OF NEW MEXICO OFFICE OF STATE GEOLOGIST SANTA FE, NEW MEXICO

INSPECTION REPORT

October 16, 1951

I. A. Stephens - Lee #1 - Sec. 32-6N-30E - Quay County.

This location was given final inspection after plugging. The surface indicated that the well-bore was properly plugged according to our recommendations. However, considerable amount of junk, casing and the pits were not covered.

I called on Mr. H. J. Lee. I inquired as to whether it was agreeable to leave the pits as they were so that we might release the Bond. He stated that he was and would give us a letter or release in this regard.

This letter was received from him October 22. We are in a position to release the bond pending receipt of samples.

ELVIS A. UTZ, Gas Engineer

STATE OF NEW MEXICO OFFICE OF STATE GEOLOGIST SANTA FE, NEW MEXICO

A thirth and the transfer with the second section of the secti

(1) The Control of the Control of Contro

្រាស់ មិន ប្រទេស ប្រទេស ប្រទេស ប្រទេស ប្រធានិសាស ប្រធានិសាស ប្រធានិសាស បានប្រធានិសាស ប្រធានិស្ស ប្រធានិសាស ប្រ ក្រុមសុខិស្ស ប្រការប្រទេស ប្រែសាស ប្រធានិសាស ប្រធានិសាស ប្រធានិសាស ប្រធានិសាស ប្រធានិសាស ប្រធានិសាស ប្រធានិសាស

> u ser **y**t dân ti Saartyr âssas