

1993 JUN 14 AM 9 21
INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2233-271F Field: Bravo Dome

Location: 1960' Fulk X 2029' FNL, T22N, R33E, Sec 27, Unit F

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>244'</u>	<u>3/4°</u>
<u>491'</u>	<u>1°</u>
<u>710'</u>	<u>1°</u>
<u>1184'</u>	<u>1 1/4°</u>
<u>1437'</u>	<u>1</u>
<u>1658'</u>	<u>3/4°</u>
<u>2158'</u>	<u>.75°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Larry J. Young (Amoco)

Boyle Dandy
Title: SITON Tool Pusher