







LEGEND:

PHASE SEPARATED HYDROCARBON THICKNESS



- MONITORING WELL
- ⦿ RECOVERY WELL
- IRRIGATION WELL
- ◆ ABANDONED WELL



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2011 ANNUAL GROUNDWATER REPORT

PHASE SEPARATED HYDROCARBON THICKNESS ISOPLETHS (FEET) SECOND SEMIANNUAL EVENT 2011

ARCADIS

FIGURE 8