

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 104 S. 4 th Street	Telephone No. 575-748-1471	RECEIVED <i>By OCD; Dr. Oberding at 10:02 am, Mar 19, 2015</i>
Facility Name Union Federal SWD #1	Facility Type Battery	

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-31412
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	8	21S	32E	1980	South	1980	East	Lea

Latitude 32.49136 Longitude 103.69418

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 B/PW	Volume Recovered 10 B/PW
Source of Release Water transfer pump	Date and Hour of Occurrence 3/9/2015; AM	Date and Hour of Discovery 3/9/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The water transfer pump could not keep up with the amount of water coming to the location, causing the storage tanks to overflow and release produced water. Wells were shut in or produced water was sent to another Salt Water Disposal facility. Vacuum truck(s) were called to recover the spill.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 30'X 20' within an unlined bermed tank battery. Vacuum trucks were called and recovered all of the produced water released. Impacted soils will be excavated /hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 100', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Hydrologist Approved by <i>[Signature]</i>	Environmental Specialist: <i>[Signature]</i> PhD
Title: NM Environmental Regulatory Agent	Approval Date: 03/19/2015	Expiration Date: 06/19/2015
E-mail Address: ACannon@yatespetroleum.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/>
Date: March 18, 2015 Phone: 575-748-4111	IRP- 25575	IRP-3568 25575

*Attach Additional Sheets If Necessary

nTO1507836361

pTO1507836537