

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Larry Marker DBA Marker Oil	Larry Marker	
PO Box 3188 Roswell NM 88202	Telephone No. 575-910-0300	
Facility Name Rose State #2	Facility Type Tank Battery	
Surface Owner State	Mineral Owner State	API No. 30-025-28772

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	5	185	34E	660	south	2080	west	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

8 BBLs * RE-EVALUATED from original list

Type of Release Crude	Volume of Release 8 BBLs	Volume Recovered 4 BBLs
Source of Release Water Leg/ Gun Barrel	Date and Hour Feb 5, 2015	Date and Hour of Discovery Feb.6,2015
Was Immediate Notice Given? NO <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? no <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

RECEIVED
By OCD; Dr. Oberding at 2:17 pm, Apr 24, 2015

Describe Cause of Problem and Remedial Action Taken.*
Cows were rubbing on water leg of gun barrel breaking it. Had already drained water from the gun barrel to replace water leg. Repairs ongoing.
Will Replace water leg and Fence Battery

Describe Area Affected and Cleanup Action Taken.*
Tank battery is burned., Spill contained. Sand soak. Scraped affected area to haul preparing site for Test

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Larry Marker 	OIL CONSERVATION DIVISION	
Printed Name: Larry Marker	Approved by Environmental Specialist: 	
Title: operator	Approval Date: 04/24/2015	Expiration Date: 07/24/2015
E-mail Address: larrym_gdc@hotmail	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides. Provide geotagged photographs of remediation.	Attached <input type="checkbox"/> IRP-3546
Date: 02/27/2015	Phone: 575-910-0300	

* Attach Additional Sheets If Necessary

8 BBLs is an Estimate, EVIDENCE of Historic Contamination will be cleaned as well.


nTO1505836213
pTO1505836449