

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ARP Production Company, LLC	Contact Randy L. Madison
Address 309 Silver St., Raton, NM 87740	Telephone No. Office 575-445-6706 Cell 575-420-1120
Facility Name: 304 Reciprocating Compressor	Facility Type: Compressor Station

Surface Owner Vermejo Park Ranch	Mineral Owner APR Production Company, LLC	API No. N/A
----------------------------------	---	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	1	31N	19E	N/A	N/A	N/A	N/A	Colfax

Latitude N 36.955 Longitude W 104.872

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 875 MCF	Volume Recovered: 0
Source of Release: PRV on Reciprocating Compressor	Date and Hour of Occurrence 4/22/17@0230	Date and Hour of Discovery 4/22/17@ 0630
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Notification was made on 4/24/17@1000 hrs.	
By Whom? Randy Madison	Date and Hour 4/24/17@1000 hrs.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
PRV failed allowing gas to vent to atmosphere. The PRV was replaced.

Describe Area Affected and Cleanup Action Taken.*
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Randy L. Madison		Approved by Environmental Specialist: 	
Title: EHS Specialist		Approval Date: 26Apr17	Expiration Date: n.a.
E-mail Address: rmadison@atlasenergy.com		Conditions of Approval:	
Date: 4/24/17	Phone: 575-445-6706	PRV failure root cause; reliability info	
			Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary