From: Bayliss, Randolph, EMNRD
To: "jeanie.mcmillan@breitburn.com"
Cc: "SHELLY DOESCHER"; "edward.pollister@breitburn.com"; Jones, William V, EMNRD
Subject: 4RP-14 Libby Mineral 1931 No 271
Date: Thursday, September 21, 2017 3:57:00 PM

Hi Jeannie

Ref http://ocdimage.emnrd.state.nm.us/Imaging/AEOrderFileView.aspx?appNo=pRAB1710942889

I'd like to get the information I need to close out this file. I need estimates of volume spilled, chlorides content, volume of soil removed and its disposal point. Any other work pertinent to that response needs to be outlined.

If the chlorides are in the 50,000 ppm range (as I tested here with a field test kit), we'll going to need some soil testing work and a delineation work plan. You might ask your environmental person to give me a call.

Randolph Bayliss, P.E.
Hydrologist, Districts III and IV
NMOCD Environmental Bureau
1220 S St Francis St, Santa Fe, NM 87505
505-476-3084, Cell 575-840-5961