

Location:	EMSU B Tank Battery	
Spill Date:	4/4/2019	
OR		
Approximate Area=	32	ft ²
Average Saturation (or depth) of Spill=	10.00	inches

Approximate Oil %	100	
Average Porosity Factor=	0.03	
Approximate Volume Recovered=	7.75	bbls

VOLUME OF LEAK		
Total Oil=	7.89	barrels
Total Produced Water=	0	barrels

VOLUME RECOVERED		
Total Oil=	7.75	barrels
Total Produced Water=	0	barrels