

Rose-Coss, Dylan H, EMNRD

From: Rose-Coss, Dylan H, EMNRD
Sent: Thursday, May 9, 2019 4:30 PM
To: 'DeAnn Grant'; Mann, Ryan
Cc: Jennifer Knowlton; Ike Tavaréz; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Final) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019

RE: (C-141 Final) Aircobra 12 State #002H Battery (30-025-40035) DOR: 04-15-2019

All,

The NMOCD tracking number for this release is 1RP-5472.

Question: was the release fully contained within the lined area, or did the spill overtop the liner?

Thanks,

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488

From: DeAnn Grant <agrant@concho.com>
Sent: Tuesday, May 7, 2019 6:59 AM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Jennifer Knowlton <jknowlton@concho.com>; Ike Tavaréz <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Final) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019

Mr. Rose-Coss/Mr. Mann,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.

Rose-Coss, Dylan H, EMNRD

From: DeAnn Grant <agrانت@concho.com>
Sent: Tuesday, May 7, 2019 6:59 AM
To: Rose-Coss, Dylan H, EMNRD; Mann, Ryan
Cc: Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant
Subject: [EXT] (C-141 Final) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019
Attachments: (C-141 Final) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019.pdf

Mr. Rose-Coss/Mr. Mann,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant
HSE Administrative Assistant
agrانت@concho.com

Rose-Coss, Dylan H, EMNRD

From: Rose-Coss, Dylan H, EMNRD
Sent: Thursday, May 2, 2019 12:50 PM
To: 'DeAnn Grant'
Subject: RE: (Final Inspection Notice) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019

Noted,

Thank you.

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488

From: DeAnn Grant <agrant@concho.com>
Sent: Thursday, May 2, 2019 12:24 PM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>
Cc: Jennifer Knowlton <jknowlton@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (Final Inspection Notice) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019

Mr. Rose-Coss,

COG Operating, LLC is giving notice that a final inspection will be conducted at the above mentioned location in two (2) business days. Please contact me if you have any questions or concerns.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



Rose-Coss, Dylan H, EMNRD

From: DeAnn Grant <agrant@concho.com>
Sent: Thursday, May 2, 2019 12:24 PM
To: Rose-Coss, Dylan H, EMNRD
Cc: Jennifer Knowlton; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant
Subject: [EXT] (Final Inspection Notice) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019

Mr. Rose-Coss,

COG Operating, LLC is giving notice that a final inspection will be conducted at the above mentioned location in two (2) business days. Please contact me if you have any questions or concerns.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



Rose-Coss, Dylan H, EMNRD

From: DeAnn Grant <agrant@concho.com>
Sent: Tuesday, April 30, 2019 1:26 PM
To: Rose-Coss, Dylan H, EMNRD; Mann, Ryan
Cc: Jennifer Knowlton; Ike Tavaréz; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant
Subject: [EXT] (C-141 Initial) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019
Attachments: (C-141 Initial) Aircobra 12 State #002H Battery (30-025-40035) 04-15-2019.pdf; Spill Calculation - Aircobra 12 State #002H Battery 04-15-2019.pdf

Mr. Rose-Coss/Mr. Mann,

Please find the attached C-141 for your consideration. The calculation sheet to determine the estimated release volume is also attached. The liquid lost estimate is based on the spill dimensions and estimated depth of fluid (wet gravel depth). The spreadsheet will calculate the volume lost in the gravel, but does not include the recovered amount in the calculation. The calculated volume in the gravel and the volume recovered were added together and reported on the C-141.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

