

## Rose-Coss, Dylan H, EMNRD

---

**From:** DeAnn Grant <agrant@concho.com>  
**Sent:** Friday, May 24, 2019 9:18 AM  
**To:** Rose-Coss, Dylan H, EMNRD; caweaver@blm.gov  
**Cc:** Griswold, Jim, EMNRD; McKinney, Deborah; jamos@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant  
**Subject:** [EXT] (Resubmittal) King Tut Federal #001H Battery (30-025-41542) 1-19-2019 (1RP-5342)  
**Attachments:** (C-141 Final) King Tut Federal #001H Battery (30-025-41542) 1-19-2019 (1RP-5342).pdf

Mr. Rose-Coss/Mr. Mann/Ms. Weaver,

Please find the attached Closure Request for the COG King Tut Federal #001H Battery (1RP-5342) release which occurred on 1/19/2019. The closure request was originally submitted to the NMOCD District 1 Office on March 28, 2019. COG is requesting that you review this closure request.

Thank you,

**DeAnn Grant**

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



CONCHO

---

**From:** DeAnn Grant  
**Sent:** Thursday, March 28, 2019 7:51 AM  
**To:** emnrd-ocd-district1spills@state.nm.us; caweaver@blm.gov  
**Cc:** jim.griswold@state.nm.us; McKinney, Deborah <dmckinne@blm.gov>; jamos@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>  
**Subject:** (C-141 Final) King Tut Federal #001H Battery (30-025-41542) 1-19-2019 (1RP-5342)

To Whom It May Concern,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

***DeAnn Grant***

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

