

## Rose-Coss, Dylan H, EMNRD

---

**From:** Rose-Coss, Dylan H, EMNRD  
**Sent:** Tuesday, June 4, 2019 10:22 AM  
**To:** 'DeAnn Grant'; Mann, Ryan  
**Subject:** RE: (C-141 Final) Corazon 4 State SWD #001 (30-025-40944) 03-01-2019 (1RP-5403)

Ms. Grant,

The NMOCD has reviewed the closure request for Corazon 4 State SWD #001 (30-025-40944) release on 03/01/2019. The available information indicates that the requirements of 19.15.29 NMAC have been met and no further corrective action is required. The NMOCD considers administrative order **1RP-5403** closed. However, this determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Thanks,

**Dylan Rose-Coss**

*Environmental Scientist*  
Oil Conservation Division  
1220 South St. Francis Drive  
Santa Fe, New Mexico 87505

(505) 476-3488

---

**From:** DeAnn Grant <agrant@concho.com>  
**Sent:** Monday, June 3, 2019 8:29 AM  
**To:** Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>  
**Subject:** [EXT] (C-141 Final) Corazon 4 State SWD #001 (30-025-40944) 03-01-2019 (1RP-5403)

Mr. Rose-Coss/Mr. Mann,

It appears I forgot to attach the Final C-141 with my request for closure.  
Please see the attached Final C-141 to accompany the e-mail below.  
I apologize for any inconvenience this may have caused.

Thank you,

**DeAnn Grant**

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



**From:** DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>

**Sent:** Friday, May 24, 2019 9:24 AM

**To:** Rose-Coss, Dylan H, EMNRD <[DylanH.Rose-Coss@state.nm.us](mailto:DylanH.Rose-Coss@state.nm.us)>; Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>

**Cc:** Jennifer Knowlton <[jknowlton@concho.com](mailto:jknowlton@concho.com)>; Ike Tavarez <[itavarez@concho.com](mailto:itavarez@concho.com)>; Robert McNeill <[RMcNeill@concho.com](mailto:RMcNeill@concho.com)>; Sheldon Hitchcock <[SLHitchcock@concho.com](mailto:SLHitchcock@concho.com)>; Dakota Neel <[DNeel2@concho.com](mailto:DNeel2@concho.com)>; Rebecca Haskell <[RHaskell@concho.com](mailto:RHaskell@concho.com)>; DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>

**Subject:** [EXT] (C-141 Final) Corazon 4 State SWD #001 (30-025-40944) 03-01-2019 (1RP-5403)

Mr. Rose-Coss/Mr. Mann,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOC approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

**DeAnn Grant**

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

