

Rose-Coss, Dylan H, EMNRD

From: Rose-Coss, Dylan H, EMNRD
Sent: Thursday, June 6, 2019 2:20 PM
To: 'Christine Alderman'; Amos, James A (jamos@blm.gov)
Subject: RE: West Grama Ridge 8-5 Fed 2H (30-025-43554)

All,

The OCD has processed the C-141 form submitted on _5/15/2019_ regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number _1RP-5532__ has been assigned. Please refer to this case number in all future correspondence.

Thanks,

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488

From: Christine Alderman <calderman@cimarex.com>
Sent: Wednesday, May 15, 2019 1:36 PM
To: Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>; EMNRD-OCD-District1spills <EMNRD-OCD-District1spills@state.nm.us>; Amos, James A (jamos@blm.gov) <jamos@blm.gov>
Subject: [EXT] West Grama Ridge 8-5 Fed 2H (30-025-43554)

All,

We had a produced water release at the above named lease. The cap on the filter for the H-pump failed causing water to spill from the tanks. The spill was not contained and impacted an area approximately 140' x 180' x 6", all on pad. The amount spilled was calculated from production numbers supplied by the pumper. The volume was 260 bbls, with 60 recovered with a vacuum truck.

A hydro vac was immediately called to location and the heavily impacted soils were removed and disposed of. Samples will be collected of the area to determine if any impact was left.

Please find attached, the C-141.

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin

Midland TX
Cell – 432.853.7059