

Rose-Coss, Dylan H, EMNRD

From: Rose-Coss, Dylan H, EMNRD
Sent: Tuesday, July 23, 2019 10:52 AM
To: 'Rebecca Haskell'
Cc: Mann, Ryan; DeAnn Grant; Dakota Neel; Sheldon Hitchcock; Ike Tavarez; Jennifer Knowlton
Subject: RE: (Extension Request) Cabo Blanco State #001H 04-23-2019 1RP-5480

Ms. Haskell,

The OCD grants a 60 day extension of time to complete delineation activities and submit a work plan or conduct remediation activities and submit a closure report, for the Cabo Blanco State #001H 04-23-2019 1RP-5480 release. The Division will expect the report or an additional extension of time request by September 21, 2019.

Thanks,

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488



From: Rebecca Haskell <RHaskell@concho.com>
Sent: Monday, July 22, 2019 1:02 PM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>
Cc: Mann, Ryan <rmann@slo.state.nm.us>; DeAnn Grant <agrant@concho.com>; Dakota Neel <DNeel2@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Ike Tavarez <itavarez@concho.com>; Jennifer Knowlton <jknowlton@concho.com>; Rebecca Haskell <RHaskell@concho.com>
Subject: [EXT] (Extension Request) Cabo Blanco State #001H 04-23-2019 1RP-5480

Mr. Rose-Coss,

Under the new spill rule a closure report is due for the above release on July 22, 2019. COG has initiated delineation activities but have not fully achieved delineation and would like to request an three month extension until October 22, 2019 to complete delineation activities and submit a work plan or conduct remediation activities and submit a closure report.

Thank you,

Becky Haskell
Senior HSE Coordinator
COG Operating LLC
600 W Illinois Avenue | Midland, TX 79701
Direct: 432-818-2372 | Main: 432.683.7443
Cell: 432-556-5130
rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rose-Coss, Dylan H, EMNRD [<mailto:DylanH.Rose-Coss@state.nm.us>]
Sent: Monday, May 13, 2019 3:10 PM
To: DeAnn Grant <agrant@concho.com>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>
Subject: [External] RE: (C-141 Initial) Cabo Blanco State #001H 04-23-2019

**** External email. Use caution. ****

All,

The NMOCD tracking number for this event is **1RP-5480**.

Thanks,

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488

From: DeAnn Grant <agrant@concho.com>
Sent: Tuesday, May 7, 2019 9:50 AM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Initial) Cabo Blanco State #001H 04-23-2019

Mr. Rose-Coss/Mr. Mann,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

