

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Incident ID	NDHR1921037218
District RP	1RP-5618
Facility ID	
Application ID	pDHR1921036715

Release Notification

Responsible Party

Responsible Party RIDGEWAY ARIZONA OIL CORP.	OGRID 164557
Contact Name WILLIAM BOYD	Contact Telephone 713-496-0986
Contact email WBOYD@PEDEVCO.COM	Incident # (assigned by OCD)
Contact mailing address 1250 WOOD BRANCH PARK DRIVE, SUITE 400, HOUSTON, TX 77079	

Location of Release Source

Latitude 33.73536 Longitude -103.48623
(NAD 83 in decimal degrees to 5 decimal places)

Site Name BROWN TANK BATTERY	Site Type TANK BATTERY
Date Release Discovered JUNE 26, 2019	API# (if applicable) 30-041-20837

Unit Letter	Section	Township	Range	County
J	05	7S	34E	ROOSEVELT

Surface Owner: State Federal Tribal Private (Name: SHANNON KIZER)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 8	Volume Recovered (bbls) 8
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 7	Volume Recovered (bbls) 7
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release
INTERNAL CORROSION ON THE PRODUCTION TANK CAUSED A LEAK TO DEVELOP ON A 2" COLLAR LOCATED ON THE REAR OF THE TANK


State of New Mexico
Oil Conservation Division

Incident ID	NDHR1921037218
District RP	1RP-5618
Facility ID	
Application ID	pDHR1921036715

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>William Boyd</u> Title: <u>Land + Regulatory Manager</u> Signature: <u></u> Date: <u>7/2/2019</u> email: <u>wboyd@pederco.com</u> Telephone: <u>713-496-0986</u>
<u>OCD Only</u> Received by: <u>Dylan Rose-Coss</u> Date: <u>07/29/2019</u>