

Rose-Coss, Dylan H, EMNRD

From: Rose-Coss, Dylan H, EMNRD
Sent: Monday, August 5, 2019 5:00 PM
To: 'DeAnn Grant'; jamos@blm.gov
Cc: dmckinne@blm.gov; Jennifer Knowlton; Ike Tavaréz; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (Resubmittal) C-141 Final Gadwall 35 Federal #001H CTB 04-26-2019 (1RP-5513)

Ms. Grant,

The NMOCD has reviewed and accepts the closure request for the Gadwall 35 Federal #001H CTB (1RP-5513) site.

Note: this determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Thanks,

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488



From: DeAnn Grant <agrant@concho.com>
Sent: Monday, August 5, 2019 3:46 PM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>; jamos@blm.gov
Cc: dmckinne@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavaréz <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: (Resubmittal) C-141 Final Gadwall 35 Federal #001H CTB 04-26-2019 (1RP-5513)

Mr. Rose Coss/Mr. Amos,

Please find the attached Closure Request for the COG Gadwall 35 Federal #001H CTB (1RP-5513) release which occurred on 4/26/19. The closure request was originally submitted to the NMOCD District 1 Office on June 6, 2019. COG is requesting that you review this closure request.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



From: DeAnn Grant

Sent: Thursday, June 06, 2019 2:38 PM

To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>; jamos@blm.gov

Cc: dmckinne@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavaréz <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>

Subject: (C-141 Final) Gadwall 35 Federal #001H CTB 04-26-2019 (1RP-5513)

Mr. Rose-Coss/Mr. Amos,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

