District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party: ETC Texas Pipeline, Ltd.

Contact email: Carolyn.blackaller@energytransfer.com

Contact mailing address: 600 N. Marienfeld St., Suite 700, Midland, TX 79701

Contact Name: Carolyn Blackaller

Received by OCD: 8/21/2019 11:52:18 AM

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM1925949313
District RP	1RP-5663
Facility ID	
Application ID	pRM1925941422

## **Release Notification**

## **Responsible Party**

OGRID: 371183

Contact Telephone: (817) 302-9766

Incident # (assigned by OCD)

Location of Release Source					
Latitude 32.11	757		(NAD 83 in dag	Longitude _	
_			(NAD 65 in dec	cimal degrees to 5 decim	nui piaces)
Site Name: 2B2-4 Pipeline				Site Type:	Pipeline
Date Release Discovered: 8/8/2019				API# (if app	olicable)
Unit Letter	Section	Township	Range	County	
O/P	S21	T25S	R37E	Lea	
Surface Owner: State Federal Tribal X Private (Name: Energy Transfer  Nature and Volume of Release					
				calculations or specific	justification for the volumes provided below)
Crude Oil Volume Released (bbls)			Volume Recovered (bbls)		
Produced Water Volume I		Volume Release	eased (bbls)		Volume Recovered (bbls)
		Is the concentrat	ion of dissolved c >10,000 mg/l?	hloride in the	Yes No
Condensate		Volume Released (bbls)			Volume Recovered (bbls)
X Natural Gas Volume Released (Mcf): 114.2 mcf		of	Volume Recovered (Mcf): 0 mcf		
Other (describe) Volume/Weight Released (provide units)		e units)	Volume/Weight Recovered (provide units)		
Cause of Rele	ease: The re	lease was attribute	ed to a pipeline stri	ike by a 3 <sup>rd</sup> -party w	orking in the area.
					-

Form C-141 Page 2

## State of New Mexico Oil Conservation Division

Incident ID	NRM1925949313
District RP	1RP-5663
Facility ID	
Application ID	pRM1925941422

Was this a major	If YES, for what reason(s) does the respon	sible party consider this a major release?				
release as defined by 19.15.29.7(A) NMAC?						
D Vac V Na						
Yes X No						
If YES, was immediate no	Lotice given to the OCD? By whom? To who	om? When and by what means (phone, email, etc)?				
Initial Response						
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury						
X The source of the release has been stopped.						
X The impacted area ha	as been secured to protect human health and	the environment.				
X Released materials ha	ave been contained via the use of berms or	likes, absorbent pads, or other containment devices.				
X All free liquids and re	ecoverable materials have been removed an	d managed appropriately.				
If all the actions described	d above have <u>not</u> been undertaken, explain	why:				
40						
*						
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Printed Name: Carolyn B	Blackaller	Title: Sr. Environmental Specialist				
Signature: Carely Mackallar		Date: <u>8/21/2019</u>				
email: Carolyn.blackaller	@energytransfer.com	Telephone: (817) 302-9766				
OCD Only						
Received by: Ramona	Marcus	Date: <u>09/16/2019</u>				