District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party: ETC Texas Pipeline, Ltd.

Contact email: Carolyn.blackaller@energytransfer.com

Contact mailing address: 600 N. Marienfeld St., Suite 700, Midland, TX 79701

Contact Name: Carolyn Blackaller

Received by OCD: 8/5/2019 10:16:30 AM

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM1928048124
District RP	1RP-5734
Facility ID	
Application ID	pRM1928048462

Release Notification

Responsible Party

OGRID: 371183

Contact Telephone: (817) 302-9766

Incident # (assigned by OCD)

Location of Release Source							
Latitude 32.25686 Longitude -103.19823 (NAD 83 in decimal degrees to 5 decimal places)							
Site Name: O-5 Pipeline					Site Type: I	Pipeline	
Date Release Discovered: 7/23/2019				API# (if app	licable)		
Unit Letter	Section	Township	Range		County		
P	31	T23S	R37E		Lea		
Surface Owner: State Federal Tribal X Private (Name: <u>Deep Wells Ranch, Inc.</u>)							
Nature and Volume of Release							
Crude Oil		(s) Released (Select al Volume Release		calculat	ions or specific	justification for the volumes provided below) Volume Recovered (bbls)	
						A control form of the second o	
Produced Water Volume Released (bbls)					Volume Recovered (bbls)		
Is the concentration of dissolved chloride produced water >10,000 mg/l?			e in the	Yes No			
Condensate Volume Released (bbls)				Volume Recovered (bbls)			
X Natural Gas Volume Released (Mcf): 129.6 mcf			f		Volume Recovered (Mcf): 0 mcf		
Other (describe) Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)			
Cause of Release: Leak due to corrosion of pipeline segment. There were no liquids associated with this release.							

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NRM1928048124
District RP	1RP-5734
Facility ID	
Application ID	pRM1928048462

release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respon	sible party consider this a major release?				
Yes X No						
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?						
Initial Response						
The responsible p	party must undertake the following actions immediately	vunless they could create a safety hazard that would result in injury				
X The source of the release has been stopped.						
X The impacted area ha	s been secured to protect human health and	the environment.				
X Released materials ha	we been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.				
X All free liquids and recoverable materials have been removed and managed appropriately.						
If all the actions described	If all the actions described above have <u>not</u> been undertaken, explain why:					
*						
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Printed Name: Carolyn B	lackaller	Title: Sr. Environmental Specialist				
Signature: Carolyy 18	bokaller	Date: <u>8/5/2019</u>				
email: Carolyn.blackaller	@energytransfer.com	Telephone: (817) 302-9766				
OCD Only						
Received by: Ramona	n Marcus	Date: 10/07/2019				