

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NRM1928436172
District RP	1RP-5742
Facility ID	
Application ID	pRM1928437030

## Release Notification

### Responsible Party

Responsible Party RIDGEWAY ARIZONA OIL CORP	OGRID 164557
Contact Name WILLIAM BOYD	Contact Telephone (713) 572-7912
Contact email wboyd@pedevco.com	Incident # (assigned by OCD)
Contact mailing address 575 N DAIRY ASHFORD RD, SUITE 210, ENERGY CENTER II, HOUSTON, TX 77079	

### Location of Release Source

Latitude 33.662951 Longitude -103.543786  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name BILBREY 23 TANK BATTERY	Site Type TANK BATTERY
Date Release Discovered 10/8/2019	API# (if applicable) 30-025-24425 is nearest well

Unit Letter	Section	Township	Range	County
L	23	9S	37E	LEA

Surface Owner: ☐ State ☐ Federal ☐ Tribal X Private (Name: DAVID ARLON BILBREY)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

X Crude Oil	Volume Released (bbls) 140.0	Volume Recovered (bbls) 30.0
X Produced Water	Volume Released (bbls) 140.0	Volume Recovered (bbls) 20.0
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	X Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release  
EXTERNAL CORROSION IN TANK BOTTOM


State of New Mexico  
Oil Conservation Division

Incident ID	NRM1928436172
District RP	1RP-5742
Facility ID	
Application ID	pRM1928437030

Was this a major release as defined by 19.15.29.7(A) NMAC?  X Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Volume in excess of 25bbl released fluid as devined by NMAC 19.15.29.7
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice provided here via NMOCD Fee Portal submission of the C-141 Email to Rick Rickman of the Hobbs OCD sent 10/9/2019 at 10:48 AM	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

X The source of the release has been stopped. X The impacted area has been secured to protect human health and the environment. X Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. X All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:     
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>WILLIAM L BOYD</u> Title: <u>LAND &amp; REGULATORY MANAGER</u> Signature: <u></u> Date: <u>10/9/2019</u> email: <u>wboyd@pedevco.com</u> Telephone: <u>(713) 572-7912</u>
<b><u>OCD Only</u></b>  Received by: <u>Ramona Marcus</u> Date: <u>10/11/2019</u>