Page 5

Oil Conservation Division

Incident ID NRM1927743918 District RP 1RP-5730 Facility ID fOY1827131144 Application ID pRM1927743126

Remediation Plan

Remediation Plan Checklist: Each of the following items must be included in the plan.	
 Detailed description of proposed remediation technique Scaled sitemap with GPS coordinates showing delineation points Estimated volume of material to be remediated Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required) 	
Deferral Requests Only: Each of the following items must be confirmed as part of any request for deferral of remediation.	
Contamination must be in areas immediately under or around production equipment where remediation could cause a major facility deconstruction.	
Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human health, the environment, or groundwater.	
Signature: Mhur fine Date	clease notifications and perform corrective actions for releases C-141 report by the OCD does not relieve the operator of nediate contamination that pose a threat to groundwater, use of a C-141 report does not relieve the operator of
OCD Only	
Received by:Cristina Eads Date:	02/12/2020
☐ Approved with Attached Conditions of Approv	al Denied Deferral Approved
Signature: Cristina Cada Dale: 02/12/2020	