

BW - _____035_____

INSPECTION

2022

From: [Fortner, Kerry, EMNRD](#)
To: [Chavez, Carl J, EMNRD](#); [Griswold, Jim, EMNRD](#); [Goetze, Phillip, EMNRD](#)
Cc: [Cordero, Gilbert, EMNRD](#)
Subject: Llano Disposal Siringo 1
Date: Monday, January 31, 2022 7:36:45 AM
Attachments: [IMG_0362.JPG](#)
[IMG_0363.JPG](#)
[IMG_0364.JPG](#)
[IMG_0365.JPG](#)
[IMG_0366.JPG](#)

I inspected the Llano Disposal Siringo ACS ST #1 Brine well on 1/24/22. All equipment and location are in good shape, the last reported production was not shown. The well is running shows 500#. Attached are the pictures.

Kerry Fortner

Compliance Officer A

EMNRD-OCD District 1

1625 N. French Drive

Hobbs, NM 88240

Office: 575-393-6161 Ext 120

Cell: 575-263-6633

kerry.fortner@state.nm.us



LLano Disposal, LLC
SIRINGO ACS ST. #1 BSW
UL D - SEC 26 - T17S - R36E
API# 30-025-30701
575-704-2777 · 575-631-8067







