

NM - 73

INSPECTIONS & DATA

Time: 11:45 Date 4-1-97

Pronghorn Sulfur Disposal System

SWD

Farming Tank Bottoms in the P.I.
Find out whether it is commercial or
centralized

Photo #17 outside Gate Signs

Photo #18 Land Farm inside pit.

Pronghorn South Battery

NW 1/4 Sec 18, T20S, R33E
(505) 392-8292

Needs to be permitted

End 11:50

Markus Kelly

Photo 13 Treeing Plants Tanks

Photo 14 2 Skel pits Hunting Coil

Photo 15 Over Flow Picket Area

Scanned Fence lined

can be with the

Drums of Non Hazardous Waste From Texas
with Non Hazardous Solvents (No Opposite)
Signs

To be Recycled Is Any Goes to Land Fill
as waste must be sampled

Photo 16 Land Fill Solids Pit Down to

Red Solids, Colchec Thin Soil Horizon

Washed Refining waste in corner
west end -

Nets are the Biggest
Smell

End 11:35

Markus Kelly

PRONGHORN SWD SYSTEM SOUTH BATTERY INSPECTION (PHOTOS BY OCD)



PHOTO NO. 1

DATE: 04/1/97



PHOTO NO. 2

DATE: 04/1/97

State of New Mexico



ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

2040 South Pacheco

P.O. Box 6429

Santa Fe, New Mexico 87505-5472

Pronghorn SWD SYSTEM
South Battery
4-1-97



Pronghorn SWD System
South Battery

4-1-97



Pronghorn SWD System

South Battery

4-1-97