

GW - 17

INSPECTIONS & DATA




SUMP AND RAMP
BEFORE DEMOLITION
FACING SOUTH

NO
SMOKING



SUMP, FACING EAST



SUMP AND RAMP
BEFORE DEMOLITION
FACING NORTH



SUMP

FACING NORTH



RAMP AND SUMP
PRIOR TO DEMONSTRATION
FACING NORTH



REMOVAL OF SUMP
FACING SOUTH



CONCRETE RAMP
BROKEN UP

FACING NORTH-EAST

7
#



SUMP, PARTIALLY REMOVED
FACING SOUTH



SUMP AREA AFTER
CONCRETE REMOVAL

FACING EAST



DEMOLITION OF SUMP
FACING NORTH



FORMER SUMP AREA
CONTAINMENT WALL TO THE LEFT
FACING DOWN



PIECE OF SIDEWALL TO
RAMP UNIT

FACING NORTH-EAST



RAMP AREA OF EXCAVATION
FACING SOUTH



RAMP AREA, SOUTH END, AFTER
CONCRETE REMOVAL.

UNKNOWN PIPE

FACING EAST



LOAD OF CONCRETE

HAULED TO NON-HAZ/CONST.
DEBRIS FACILITY



EXCAVATION OF NORTH END

FACING NORTH-EAST



DEEPENING NORTH END OF
EXCAVATION ~ 10' BGS.

FACING NORTH-EAST



EAST SIDEWALL OF
NORTH END EXCAVATION
FACING NORTHEAST



NORTH WALL OF
NORTH END EXCAVATION

FACING NORTH



WEST SIDEWALL OF
NORTH END EXCAVATION
FACING NORTHWEST



VIEW OF EXCAVATION,
FORMER RAMP AREA
IN FOREGROUND

FACING NORTH-WEST



FINAL STOCKPILE AND
EXCAVATION

FACING NORTHWEST



EXCAVATION AND STOCKPILE.
BARRICADED AND TAPED
FACING NORTH